



Mosaic Fertilizer Integrated Land Management Plan Restoration Review Agency Meeting

Wednesday, October 29, 2008

AGENDA

Introduction: Clayton, Robertson, VHB

Jeff Stewart, Mosaic

Annual Report Comments/Agency Input

Updates: Archie Creek Relocation and Mitigation

North Parcels

Stack Buffer

Field Review:

Discussions: Comments

Recommendations



Date: 10/29/08

Revised:

Source: 2007 SWFWMD Aerials

Mosaic
Archie Creek
Hillsborough County, Florida
Annual Restoration Review Agency Meeting

Vanasse Hangen Brustlin, Inc.



8043 Cooper Creek Blvd.
Suite 201
University Park, FL 34201





Figure 1
Archie Creek Mitigation Overview
Annual Restoration Review Agency Meeting






Figure 3
South Mitigation Area
Annual Restoration Review Agency Meeting



Photo Date: September 2006

DATE: 09/17/07

REVISED: 10/29/08

Aerial Photograph of Mitigation Area
Mosaic
Hillsborough County, Florida
Annual Restoration Review Agency Meeting



Vanasse Hangen Brustlin, Inc.

8043 Cooper Creek Blvd.
Suite 201
University Park, Florida 34201



Photo Date: September 2006

DATE: 09/17/07

REVISED: 10/29/08

Aerial Photograph of Mitigation Area
Mosaic
Hillsborough County, Florida
Annual Restoration Review Agency Meeting



Vanasse Hangen Brustlin, Inc.

8043 Cooper Creek Blvd.
Suite 201
University Park, Florida 34201

**Archie Creek
Annual Restoration Review Agency Meeting**

September

2006
Photo Station 1
Looking East



2008
Photo Station 1
Looking East



**Archie Creek
Annual Restoration Review Agency Meeting**

September

2006
Photo Station 1
Looking North




2008
Photo Station 1
Looking North



**Archie Creek
Annual Restoration Review Agency Meeting**

September

2006
Photo Station 1
Looking Northeast



2008
Photo Station 1
Looking Northeast



**Archie Creek
Annual Restoration Review Agency Meeting**

September

2006
Photo Station 1
Looking South



2008
Photo Station 1
Looking South



**Archie Creek
Annual Restoration Review Agency Meeting**

September

2006
Photo Station 1
Looking Southeast



2008
Photo Station 1
Looking Southeast
North Mitigation Area



**Archie Creek
Annual Restoration Review Agency Meeting**

September

2006
Photo Station 2
Looking North



2008
Photo Station 2
Looking North
North Archie Creek



**Archie Creek
Annual Restoration Review Agency Meeting**

September

2006
Photo Station 2
Looking South



2008
Photo Station 2
Looking South



**Archie Creek
Annual Restoration Review Agency Meeting**

September

2006
Photo Station 3
Looking Northwest



2008
Photo Station 3
Looking Northwest



**Archie Creek
Annual Restoration Review Agency Meeting**

September

2006

**Photo Station 3
Looking South-Southwest**



2008

**Photo Station 3
Looking South-Southwest**



**Archie Creek
Annual Restoration Review Agency Meeting**

September

2006
Photo Station 3
Looking West



2008
Photo Station 3
Looking West



**Archie Creek
Annual Restoration Review Agency Meeting**

September

2006
Photo Station 3
Looking West Northwest



2008
Photo Station 3
Looking West Northwest



**Archie Creek
Annual Restoration Review Agency Meeting**

September

2006
Photo Station 4
Looking East



2008
Photo Station 4
Looking East



**Archie Creek
Annual Restoration Review Agency Meeting**

September

2006
Photo Station 4
Looking West



2008
Photo Station 4
Looking West

