

Archie Creek
First Annual
Mitigation Area Monitoring
September 2007

VHB Project No. 65653.00



Photo Station 1 - Looking North



Photo Station 1 - Looking Northeast

Archie Creek
First Annual
Mitigation Area Monitoring
September 2007

VHB Project No. 65653.00



Photo Station 1 - Looking East



Photo Station 1 - Looking Southeast

Archie Creek
First Annual
Mitigation Area Monitoring
September 2007

VHB Project No. 65653.00



Photo Station 1 - Looking South



Photo Station 2 - Facing South

Archie Creek
First Annual
Mitigation Area Monitoring
September 2007

VHB Project No. 65653.00



Photo Station 2 - Facing North




Photo Station 3 - Looking Northwest

Archie Creek
First Annual
Mitigation Area Monitoring
September 2007

VHB Project No. 65653.00



Photo Station 3 - Looking West-Northwest



Photo Station 3 - Looking West

Archie Creek
First Annual
Mitigation Area Monitoring
September 2007

VHB Project No. 65653.00



Photo Station 3 - Looking South-Southwest

Archie Creek
First Annual
Mitigation Area Monitoring
September 2007

VHB Project No. 65653.00



Photo Station 4 - Facing East



Photo Station 4 - Looking West